

ATAMI Standard Operating Procedure

LPKF Microline 2820P Laser Cutter

Last saved by Randy Greb on 6/21/2019 4:10 PM

Revision	Date	Description/Change	Curator
0	May 14, 2019	New document	Randy Greb
1	June 19, 2019	Added additional information about DXF file conversions and Tool library setups.	Randy Greb
2	August 21, 2019	Added recipe example, added notes regarding sample thickness, cleaned up some formatting.	Randy Greb
3	11/4/2019	Updated contents to make it easier to read. Added a procedure for making parts that can translate to DXF files for milling.	Randy Greb



Contents (you can click on the title to go to the subject page)

Scope:
System Specifications:
Safety
Training Requirements
Procedures
Convert a Solidworks part to DXF for full cut-through:4
Use the Design Studio Workstation to convert DXF to LMD format for use on LPKF:5
How to Load a Flat sheet in the laser:7
How to Process a Cut Through:8
Startup Procedure:9
Shutdown/standby Procedure:11
How to Edit Tool Libraries:11
How to Use Solidworks to create a DXF file for milling:12
Standard or Example Recipes
Example of Recipe for cutting Stainless Steel Shims:15
Basic Troubleshooting17
If you get startup errors or hear beeping from the system:17
Hints for addressing laser burn quality issues:
Attachments
LPKF User Interface button functions19
Health Hazards:
Examples of what type of shape goes with which Modify Choice:
Creating and Editing Tool Libraries:22
Information on Sample Size:

Scope:

Operations of the laser including:

- How to prepare files
- How to run standard recipes for cutting
- How to update your specific recipes
- Advanced applications such as circuit board cutting, via hole cutting, fiducial alignments.

System Specifications:

Please see the system description the ATAMI website for general specifications of this system.

<u>Safety</u>

General

Laser energies and pinch hazards are present in this sytem. Use extreme caution when opening and closing the door and <u>never defeat any laser interlocks</u>.

PPE Required

Safety glasses

<u>Nitrile gloves should always be used for handling and cleaning samples</u>. Samples may have contaminants as a result of the laser cutting.

Hazardous Energies

Electrical

Only ATAMI staff and qualified supplier maintenance personnel are allowed to open outside panels and work on the system. All electrical hazard controls must be in place for maintenance. General users are not allowed to open system panels.

Mechanical

Use caution when loading and unloading samples to avoid getting pinched.

Stored/Potential

Laser radiation is present in this system. Never operate the system without the front cover and all other safety protections in place.

Thermal

Laser cutting may generate heat on the sample surface. Use caution when removing the sample after cutting.

Direct exposure to laser radiation can cause burns.

Materials/Consumables Hazards

Use caution when removing cut samples. Always use nitrile gloves when handling cut samples.

If appropriate use 100% IPA and a white Texwipe towel to clean the sample and the surface of the vacuum stage after cutting.

Interlocks

Interlocks are in place to prevent exposure to laser radiation and the moving stage. Never defeat interlocks.

Training Requirements

- 1. Pass all ATAMI required safety courses
- 2. Finish lab tour with qualified ATAMI trainer.
- 3. Complete all hands on training for this system and signed off by trainer.
- 4. Verify access to this document for reference.

Procedures

Convert a Solidworks part to DXF for full cut-through:

Step	Action	Notes
1	In Solidworks, open the file an orient the part to the plane that you want to cut.	
2	Choose the "File-Save As" menu and safe file as type "DXF".	File name v Save as type Drf (*.dd) Description: Add a description
3	After you click "Save", you'll need to click the green check sign to export the current view, as shown here.	DXF / DWG Output DXF / DWG Output DXF / DWG Output Export Faces / loops / edges Annotation views Views To Export Front Select All Output Alignment X axis: X axis: X axis: Select All Export Options Single file Separate files
		Output Alignment Image: Constraint of the state of





4	The next step allows you to remove unwanted entities (this mainly applies to the border). Select unwanted entities by clicking on them. To select multiple lines hold down the "Ctrl" key while clicking. To remove entities, click "Remove Entities".	DUT-OWS Change - "Current
5		
6	Click save to finish.	

Use the Design Studio Workstation to convert DXF to LMD format for use on LPKF:

Step	Action	Notes
1	Log in with the following account: Username: " .\b11guest " Password: " b11guest "	
2	Open CircuitCam 6.2 with the desktop icon:	CircuitCAM 6.2
3	Select "File->Import" and use the DXF file you created earlier. Change the units to match your imported part. For example, if you are using inches, change "Unit" to 1 inch and press update size. For mm sizes, just leave as 1mm.	OK Cancel Size x, y 25 x 10 mm Unit 1 mm Update Size DXF-Import: Filled dirdes
4	Select "Select->All" (or ctrl-A) to select your entire drawing.	



Step	Action	Notes
		Im deplone 50 percent scale down can * - (Cruth CAM Laser Yiew Jrusen Select Tool path Modify Display Library Septings 1: Solar - 00, 120 Solar - 00, 120
5	Use the drop-down list box that is on the screen under the Library and Settings menus to pick the cut type. Use the last of the four "Contour_ThroughCut_R" options. This is the current default. As more analysis is completed, the suggestions for additional options will be added.	Image: State of the second state of
6	Select one of the following: "Modify->convert to closed line path (shift-W)" – for objects such as closed boxes, dogbone structures, discs, "Modify->Convert to One Flash (shift-H): - for complicated cuts with multiple shapes that may not intersect. See attachment below for examples.	ne_50_percent_scale_down.cam * - CircuitCAM Laser sert Select Tool path Modify Display Library Settings Help Curve Path to Polygon Shift+P Combine to Polygon Ctrl+K Convert to Polygon Shift+V Convert to Closed Outline Path Shift+W Denest polygonCutOut Shift+I Denest cutOut Shift+I Denest cutOut Shift+J Convert to Circle Shift+K Draw to Flash Shift+D



Step	Action	Notes
7	Select "Tool Path -> Laser Scanner"	Laser Scanner Center objects on source layer: Cover fiducates on layer: Size max X: 50 mm Make sure that the drop down menu has the correct "Contour_ThroughCut" option. This should be the outermost "Contour_ThroughCut" you used. If you only used one, select that one. The values in "max X" and "max Y" fields do not need to be changed. Select "OK"
8	Select "File->export->LPKF- >MicroLineDrill" The file will be exported to the same location as the file that was imported.	File Edit Yiew Insert Select Tool path Modify Display Library Settings He New Import Import
9	Close the CircuitCam application, log off the computer and sign out of the card scanner.	

How to Load a Flat sheet in the laser:

Step	Action	Notes
1	Put the stage in the home position.	Refer to the attachment below for a descriptions
		of the LPKF user interface buttons.



Step	Action	Notes
2	Turn on Vacuum and let the system sit for 30 seconds.	This will clear any residual contaminants from the
		previous cuts.
3	Move the stage to the exchange position.	Use caution, this will open the front door.
4	Wipe the vacuum surface with a Texwipe white towel and	This improves vacuum, prevents cross-
	IPA to clean it of particles and contaminants.	contamination and
5	Place your sheet on the surface. If it does not cover the	
	whole surface, you can use some of the plastic sheets to	
	cover open areas and improve vacuum on your sample.	
6	Turn on the vacuum and press the door button to close	
	the door.	

How to Process a Cut Through:

Step	Action	Notes
1	Select "File" \rightarrow "Import" \rightarrow "LMD/LPR"	
2	Select your file then click "Open"	
3	Select "OK" at the Import message box.	At least one tool not assigned ! Enter the Edit Tool Assignment dialog box to complete assignment !
4	From the menu bar, select "Job" \rightarrow "Material"	
5	Enter the correct material thickness in "Thickness" and then press OK.	Material Low corner Waterial Low corner Image: Size High corner 0 0 Size 0 0 Free drive level [mm] 0 Free drive level [mm] 0 <
6	From the menu bar, select "Job" → "Tool Assignment…"	



Step	Action	Notes
7	Select the "Tool Library" you want to pick your tool	
	from.	
8	Select the "Tool Name" that you want to use.	
9	Select the "Phase" that you want to use. If you have	
	only one phase, leave the phase assignment as is. If	
	you have multiple phases, the phase with the lower	
10	Select "OK"	
10		
11	Move your part to the desired location on the sheet that you loaded.	
	the location of the target on the display	
	the location of the target on the display.	position
		Select and move a part
		Select and copy a part Mov hom
		This button works by pressing it, then placing the cursor over your part, holding down the left mouse button, and moving it. It's not intuitive at first, but once you do it a couple of times, it's straightforward.
12	To ensure that you part is aligned as desired click	A red light will flash around the perimeter of your part
12	"Show limit".	The scanning field, where the red light flashes, is larger than the area which will be cut.
13	Press the start button to start the cut job.	The display will show progress and let you know when it is done.
		If you need to stop the job (if it is in the incorrect location), then you can press this button again to stop it.

Startup Procedure:



	Shutuowny Standby Procedure.		
Step	Action	Notes	
1	If you plan to use the tool within the day, you can leave		
	the tool started up after you are done with our first		
	sample.		
2	If it is Friday after 1pm,		
	Go ahead and shutdown the software first.		
	Then after the software has fully closed, press the power button.		

Shutdown/standby Procedure:

How to Edit Tool Libraries:

Step	Action	Notes				
Step 1	Action Select "Edit->Tool Library", and pick the library you need to edit.	Notes You may need to edit tool libraries for different material properties, thickness, or cut features. Never edit tool properties for Tool Libraries that are not owned by you. You must have your own tool library befored the editing. LPKF CircuitMaster [MicroLine 2820 F File Edit View Job Configuration 0.25 ss shim.3fl 1 2fl				
		Mark All Cancel Marking Cancel All Marking Tool Library Ctrl+T > Phases	10.3fl 11.3fl 15.3fl 16.3fl 17.3fl 18.3fl 2.3fl 26.2fl			

Paste

Copy

40 6

2	You will then get to the tool library editing	Tool priority 1 Change	Task 1 Note
	screen.	No. Tool 1 Fiducial 2 Oct ext compose 210 m	1. Laser parameters
	You will need to c reference the LPKF User manual and run experiments to determine the effects of these parameters on your materials and how they affect your cut. Laser parameters and Scanner parameters have the most impact. Many people use multiple tasks, with the same laser/scanner parameters and different "Tool Z- offset" to work through thick materials. By moving z-position up (stage up), the laser will be focus deeper in to the samele	Cut out copper 210um	Current [A] Frequency [kHz] Power [M] 2. Scanner parameters Jump delay [µs] Laser of delay [µs] Laser of delay [µs] Mark delay [µs] Mark delay [µs] Mark delay [µs] 3. Type of circle 4. Start moves 5. End moves 5. End moves 6. Wobble 7. Process parameters Air pressure repeatition Tool delay [ms] Tool Z-Offset [µm]
		Save as	Service Finable Ta

How to Use Solidworks to create a DXF file for milling:

Step	Action	Notes
1	Create an extruded boss base.	Image: Second

7	Then, after saving the solidworks file, save it as a DXF file and use the current view.	Export Faces / loops / edges Image: Imag
8	Then use Circuit CAM to convert to an LMD file.	You'll need to use the "Modify->Convert to One Flash" option.
9	Then develop a throughcut Tool Library and tool that will cut the lines and thus mill material to the depth of interest.	

Standard or Example Recipes

Example of Recipe for cutting Stainless Steel Shims:

	Test					
Test Group	Parameter	Recommended	Range			
NA	Tool Name	ххх	xxx	304_4mil	304_8mil_standard	304_8mil_fine
Laser						
parameters	Current (A)	displayed	displayed	100	75	75
Laser	Frequency					
parameters	(kHz)	100	25-200	9.54	11	10
Laser						
parameters	Power (W)	displayed	displayed	2000	2000	2000
Scanner	Jump delay					
parameters	(us)	1000	1-1,000,000	1	1	1
	Jump					
Scanner	speed					
parameters	(mm/s)	=mark speed	1-6,000	100	100	100
Scanner	Laser off					
parameters	delay (us)	100	2-1,000	0	0	0
Scanner	Laser on					
parameters	delay (us)	50	0-1,000	2000	2000	2000

Scanner	Mark delay					
parameters	(us)	600	1-10,000	600	600	600
	Mark					
Scanner	speed					
parameters	(mm/s)	depends	1-2,000	250	250	250
Scanner	Polygon					
parameters	delay (us)	50	0-1,000	No	No	No
Start						
moves	Active	No	Yes/no	1	1	1
Start	Length					
moves	(um)	1	1-n	jump	jump	jump
Start						
moves	Туре	jump	jump	No	No	No
End moves	Active	No	Yes/no	1	1	1
	Length					
End moves	(um)	1	1-n	jump	jump	jump
End moves	Туре	jump	jump	yes	yes	yes
Process	Air					
parameters	pressure	no	Yes/no	20	20	20
Process						
parameters	Repetitions	1	1-n	20	40	30
Process	Tool delay					
parameters	(ms)	0	0-n	0	0	0
			0-11mm			
			(depends on			
Process	Tool Z-		sample			
parameters	offset (um)	0	thickness)			
	Top Image			20	20	20
	Beam					
Type of	Diameter					
circle	(um)	20	depends	1	1	1
	Circle					
Type of	Diameter			_	_	
circle	Factor	1	1	0	0	0
	Circle Inner					
Type of	Diameter					
circle	(um)		depends	outer	outer	outer
Type of	Circles					
circle	type	Outer Circle	depends			
Type of		1.11	ala	4		
circle	File name	blank	aepenas	1	1	1
Type of		4	al a la circel a			
CITCIE	NO OT TURNS	L	aepenas	no	no	no
Type of		NI -	Magler	0		<u>_</u>
circle	Outward	NO	Yes/no	U	0	U

(back to contents)

TAMI

Type of	Overlap				
circle	(um)	0	depends		

Basic Troubleshooting

If you get startup errors or hear beeping from the system:

Step	lf	Then	Notes
1	1You get startup errors.Press the status button to get the Fault Monitor Display and then press "Clear faults".		Time Client Unit Type Code Description Accepted * *16.05.20 IO Board Fault 6027 Releasing li 16.05.2019, 11:37:14 * *16.05.20 IO Board Fault 6028 Error limits 16.05.2019, 11:37:14 * *16.05.20 IO Board Fault 6029 Error limits 16.05.2019, 11:37:14 * *16.05.20 IO Board Fault 6030 Error limits 16.05.2019, 11:37:14 * *16.05.20 IO Board Fault 6030 Rarge error 16.05.2019, 11:49:40 *16.05.20 IO Board Fault 6026 Homing limit 16.05.2019, 11:49:40 *16.05.20 IO Board Fault 6028 Error limits 16.05.2019, 11:49:40 *16.05.20 IO Board Fault 6028 Error limits 16.05.2019, 11:49:40 * *16.05.20 IO Board Fault 6028 Error limits 16.05.2019, 11:49:40 *
		Do not press "Remove all checked faults".	OK Cereal Coartuals Remove alcheckertuals
2	You cannot clear them.	Contact ATAMI staff.	

Problem	Possible cause	Remedy
Laser beam burns at the starting points	Laser - ON - delay too short	Laser ON - increase delay
Laser beam burns at the end points	Laser -OFF - delay too long	Laser OFF - reduce delay
When structuring closed lines there are remaining webs	Starting point Laser - ON - delay too long	Laser ON - reduce delay
Structures are not lasered completely	End point Laser - OFF - delay too short	Laser OFF - increase delay
At the structure start an inlet or overshoot is visible	Jump - delay too short	Jump - increase delay
Corners of polygons have been rounded off	 Polygon - delay too short 	 Polygon increase delay
	 Mark - speed too high 	 Mark reduce speed
Burn-in effects at the endpoints of the polygon vector	Polygon - delay too long	Polygon - reduce delay

Hints for addressing laser burn quality issues:

Attachments

LPKF User Interface button functions

- 1 Power Management
- 2 Display/Selection of the current production phase
- 3 Display/Selection of the current tool, that is used for the current production phase.
- 4 Configuration phase
- 5 Camera light (button active: white light, not active: red light)
- 6 Configuration active tool library
- 7 Vacuum ON/OFF
- 8 Height measurement 9 Mark speed adjustment (+/- 10 %)
- 10 Go to pause position 11 Go to home position
- 12 Displays the process data with the pilot laser
- 13 Displays the status of the automated loading system (only for ML 2000 Si, ML 2000 Ci, see page 68)

- 14 Display status
- 15 Count of job runs in batch mode (only for ML 1000 and ML 2000 P/S)
- 16 Start/Stop working process (see page 32)
- 17 Go to work piece replace position
- 18 Remove LMD data
- 19 Copy, select, mark or displace objects
- 20 Displays the position of the processing table
- 21 Up/Down Z axis
- 22 Manual moving worktable
- 23 Move laser head via mouse
- 24 Zoom function
- 25 File functions (new, import, export, open, save)

атамі

Health Hazards:

Safety notes

Danger to life!

Missing or inadequate fuse protection may result in deadly electric shocks and/or cause fire.

N e v e r bridge the automatic fuse switch!

Risk of injury!

Since the materials you are handling with have a small size and razor-sharp rough edges, a big risk of injury exists.

Make sure to wear protective gloves!

Health hazard!

Direct contact of the laser beam with the skin results in intensive burn and causes invisible interior injuries. Diffused light which contacts your skin over a space of time takes the same effects as well.

Beware in any case of direct contact between the laser beam and the skin.

Health hazard!

Hazardous substances can be generated when materials are processed by the laser beam. These may be cancer-causing.

Only use materials which are approved by LPKF for work with and always activate the provided extraction system during operation.

Health hazard!

All safety measures which are described in the material safety data sheets must be strictly adhered to!

Keep the safety data sheets near by the system. It is necessary to read the safety data sheets carefully and to adhere to all required safety measures.

Examples of what type of shape goes with which Modify Choice:

Convert to Closed Line Path:

Convert to One Flash:

Creating and Editing Tool Libraries:

You can create and edit tool libraries from the "Edit->Tool Library" drop down menu in the Circuit Master software on the LPKF computer. Refer to the manual and the attachments here for editing guidelines.

Never edit a Tool Library that was not created by you.

Recipe development spreadsheets and tool characterization whitepapers are available from ATAMI staff.

Information on Sample Size:

- The range of Z for the station is 0-11mm. The stage is at 11mm when it's at the top, and the 0mm at the bottom (furthest away from the lens).
- The top of the Porex plate is at roughly 8.4mm. This is where optical and laser focus is set.
- If you have a sample that is 5mm thick, the stage will move to roughly 3.4mm.
- The maximum sample thickness that can be cut in focus will be roughly 8.4mm.

• If you need to do cuts or marks on samples that are thicker than 8.4mm, then it will be out of focus, or we will need to develop a custom sample holder.